

SSO Maintenance Report

Date of Occurance	Address	Blockage Reason 1	Blockage Reason 2	Volume/Gallons	Responsibility	Removal Method	Receiving Waters	Mitigation Used on Untreated Waters	Actions to mitigate future SSO
01/06/15	18809 Kings	Undetermined	Tree roots	100	Homeowner				
02/04/15	18853 Carson Dr	Undetermined		5	Village	Sewer Jet			Line maintenance
02/13/15	1634 Burr Oak	Undetermined		2	Homeowner				
02/13/15	2120 Cedar	Tree roots		2	Village	Sewer Jet			Line maintenance